KEEP THIS SAFETY CARD CLOSE TO THE OPTX[™] SYSTEM AT ALL TIMES SAFETY CARD MUST BE IN THE OPERATOR'S FIELD OF VISION AT ALL TIMES



1-866-931-9730

PWSService@millerwelds.com MillerWelds.com/optxinfo



QUESTIONS?

Read and follow all labels and the Owner's Manual carefully before installing, operating, or servicing unit. Read the safety information at the beginning of the manual and in each section.

WEAR LASER SAFETY EYEWEAR


WEAR OPTX LASER WELDING HELMET



Everyone present during laser operation must wear both Miller OptX laser welding helmet and laser safety eyewear certified for OD 7 or greater at 1070 nm.

WEAR PROTECTIVE CLOTHING








Wear the supplied Miller OptX laser welding helmet to protect eyes and head. Hot flying particles, intense light, UV radiation and vagrant laser radiation can occur during material processing. Always wear the OptX laser welding helmet in combination with the appropriate laser safety eyewear.

WEAR PROTECTIVE GLOVES



Wear laser- and heat-resistant protective gloves.



SEE OTHER SIDE FOR INFORMATION ON OPERATION

KEEP THIS SAFETY CARD CLOSE TO THE OPTX[™] SYSTEM AT ALL TIMES SAFETY CARD MUST BE IN THE OPERATOR'S FIELD OF VISION AT ALL TIMES

SAFE OPERATION REQUIRES


- **1** PROPER MODE SELECTION BASED ON MATERIAL AND THICKNESS
- 2 PROPER NOZZLE SELECTION BASED ON JOINT GEOMETRY
- **3** PROPER POSITIONING OF THE OPTX TORCH (WELDING HEAD)

WELDING AND CLEANING NOZZLE SELECTION



OPTX TORCH ANGLE AND POSITION

The operator must be aware of reflections at all times. Increased occurrence of reflections is possible when laser parameters are incorrectly set to melt the target material.



SEE OTHER SIDE FOR SAFETY INFORMATION



