
## **NEW: XMT® 350 FIELDPRO™ WELDING SYSTEMS**





## **SELECTING THE RIGHT SYSTEM**

TO ENSURE YOU SELECT THE RIGHT SYSTEM: 1. First, select the accessories you need. 2. These accessories will then help you select the appropriate power source.



<sup>\*</sup>The PipeWorx 350 FieldPro will be replaced with the XMT 350 FieldPro Polarity Reversing model in 2018.