

Never use oil or petroleum base grease on regulators, inlet and outlet connections, cylinder valves, torches, fittings or other equipment in contact with oxygen.



"I told you, some of the welders were using oil on their regulators."

