

Millermatic 355 Software Update Release Notes

Version 1.2 – April 2024

New Software Versions

Weld Controller – 83685

Release Notes

- Fixes bug related to run-in and burnback
-

Version 1.1 – November 2023

New Software Versions

User Interface – 82134

Weld Controller – 82134

Graphics – 0x5DF6B757

Weld Programs – 0x2E142B59

Release Notes

- Updates to weld starts to improve aluminum performance
 - Enabling adjustable hotstart for all MIG and Pulse MIG wires (was previously aluminum only)
 - Reduced minimum WFS to 25 IPM to allow for slower run-in
 - Added System Menu setting for Auto-Set disable
 - Added serial number and software version info to exported USB logs
 - Changed TIG Trigger Error message to 10-Pin Trigger Fault
 - Bug fixes related to Invalid Weld Data error occurring during machine setup.
 - Bug fixes related to errors occurring during operation with remote pot WFS adjustment disabled
-

Version 1.0

Software Versions

User Interface – 71957

Weld Controller – 71957

Graphics – 0xF4363C17

Weld Programs – 0x5A5E1589

Release Notes

- Product launch